



a)



m_s : mother solution
 m_c : crystals



d)

McCabe loven:

- Vekst rate er uavhengig av størrelse
- Konstant oversmetting

$$G = \frac{\Delta L}{\Delta \tau} = K \Delta C_A$$

$$\Delta L = G \cdot \Delta \tau$$